Patton Memo
Products Unavailable Until Further Notice

Products Affected

- **Model 1180** Multimode Fiber Optic Modem
- **Model 1184** Multimode Fiber Optic Modem
- **Model 1185** Multimode Fiber Optic Modem
- **Model 1186** G.703 Multimode Fiber Optic Modem

Reason

Our Supplier has discontinued a key component used in this line of fiber optic products. Patton Electronics has not yet found an exact replacement. However, we are making every effort to find a solution so we can continue supplying our customers with these fine products.

Action

Patton Electronics will not be taking orders on these products until further notice.

Alternate Products

None

Related Products

Single mode fiber Modem Model 1193, and Model 1194 Fiber Optics Multiplexer.

PATTON Electronics Co.
7622 Rickenbacker Drive, Gaithersburg, MD USA 20879
Phone 1.301.975.1000 Fax 1.301.869.9293
http://www.patton.com